

## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 8

999 18th STREET - SUITE 500 DENVER, COLORADO 80202-2466



## **ACCESS AGREEMENT**

PROPERTY ADDRESS:  4646	
the north Denver area. EPA is conducting	an investigation of possible metals contamination in soils ing this investigation as part of its responsibilities under the Compensation and Liability Act, a law also referred to as
"Superfund".  Mary Acevedo	9-11-99 Date
Mary Acevedo Print Name  Mary Acevedo Signature  Acevedo	Date  303-295-0136  Phone Number
Please check the following if applicable:	portion of the sample, called a "split sample," that I may have
If you have any questions, please contact To Morrison Knudsen Corporation (EPA's contract	ed Fellman at (303) 312-6119, or Marta Valentine from the etor) at (303) 948-4693.

Your Comments:

## PLEASE SIGN AND RETURN THIS ACCESS AGREEMENT TO OUR CONTRACTOR:

Morrison Knudsen Corp., Attn: VBI70, 10822 W. TOLLER DR., LITTLETON, CO 80127.

Soil sampling will take about 1 hour. The owner or resident need not be present. If you would like to be notified when we plan to sample your property, please state so in the Comments section and provide your phone number. Also, pet owners are asked to provide a phone number so that if necessary we may schedule the sampling at a time when the pet will be indoors or restrained. Thank you for participating in this important study of your neighborhood.

NOTE: If you are <u>not</u> the current property owner, and you are not a renter who wishes to forward this request to the owner, pleas e state so in the Comments section and return this agreement unsigned.

indinilad of

E - (10%